

Accessoires for sensors



MA.Pa-06

Installation set for pressure sensors, incl. duct connectors, pressure hose and fixing screws for IY.Nc-P..., IY.Ex-P..., IR.Nc-P... und IR.Ex-P...

TH.VA-....

Thermowell, stainless steel, G ½ ', different lengths available



SC.Pu-01

M12 sensor cable, 5-wire, shielded, 1 meter

SC.Pu-05

M12 sensor cable, 5-wire, shielded, 5 meter

SC.Pu-10

M12 sensor cable, 5-wire, shielded, 10 meter



CS.Ms-M12

M12 connector set for on-site cables 5-wire, shielded, one set = 2 connectors

Accessories Calibration

KA.Pi

Calibration of humidity, temperature, pressure sensors in our in-house calibration laboratory including factory certificate (on request)